
CABLE ASSEMBLY PROCEDURE				
P/N 22-0200-1201				
PAGE 1 DF 1	DATE: 08/28/98			
DRAWN: EK	APPROVED: HN			
FOR USE WITH RG 58, 141, 303 CABLE				




	В
T. 06770	

REV	DESCRIPTION	DATE	APPR
Α	REL, ECN 4672	08/28/98	HN
В	REL. ECN 4698	09/16/98	HN

22 GREAT HILL ROAD, NAUGATUCK, CT. 06770 PHONE: (203) 729-9090 FAX: (203) 723-1794




STEP 1
TRIM CABLE TO DIMENSIONS SHOWN.
TIN CENTER CONDUCTOR.




STEP 2

SLIDE FERRULE AND SHRINK TUBING OVER CABLE. FLAIR BRAID BY ROTATING DIELECTRIC. SLIDE CONTACT ONTO CENTER CONDUCTOR AND BUTT AGAINST DIELECTRIC. SOLDER CONTACT TO CENTER CONDUCTOR AND CLEAN SOLDER JOINT.



STEP 3
SLIDE BODY OVER CABLE DIELECTRIC AND UNDER
BRAID, UNTIL CABLE BOTTOMS. SLIDE FERRULE UP
AGAINST BODY AND SOLDER, CLEAN SOLDER JOINT.



STEP 4
SLIDE SHRIK TUBING OVER FERRULE AND BODY AND HEAT INTO POSITION.

