


## **CABLE ASSEMBLY PROCEDURE**

Step 1 Trim cable to dimensions shown. Tin dip cable to dimension shown for three seconds maximum.

В


Α




В

Α


Step 2 Slide ferrule over jacket. Flare the braid by rotating dielectric.



Step 3 Install the cable into the plug assembly by; inserting the dielectric into the wedge and the flared braid over the wedge, as shown. Solder the conductor to the center contact. Clean.



Step 4 Seat ferrule on body, crimp ferrule with M22520/5-03 daniels Y-196, .128 hex.



WARNING - THIS DOCUMENT CONTAINS TECHNICAL DATA WHOSE EXPORT IS RESTRICTED BY THE ARMS EXPORT CONTROL ACT (TITLE 22, U.S.C., SEC 2751, ET. SEQ.) OR THE EXPORT ADMINISTRATION ACT OF 1979, AS AMENDED, TITLE 50, U.S.C., APP 2401 ET SEQ. VIOLATIONS OF THESE EXPORT LAWS ARE SUBJECT TO SEVERE CRIMINAL PENALTIES. DISSEMINATE IN ACCORDANCE WITH PROVISIONS OF DOD DIRECTIVE 5230.25.

Filename: ver2\Autodesk Inventor Data Base\Assemblies\28 Series\28-0080-2400-CAP.idw The **PHOENIX** Company of Chicago, Inc. APPROVALS DATE 22 GREAT HILL RD., NAUGATUCK, CT 06770 WWW.PHOENIXOFCHICAGO.COM DO NOT SCALE PRINTS 6/19/2020 CA TOLERANCES ARE: PHONE: (800) 323-9562 FAX:(630) 206-1801 FRACTIONS: ± 1/64
DECIMALS: .XX ± .01
.XXX ± .003
ANGLES: ± 1/2 CHECKED SG 9/8/2021 TITLE CABLE ASSEMBLY PROCESS FOR: 9/8/2021 VI THE INFORMATION AND DESIGNS DISCLOSED IN THIS DOCUMENT ARE CONFIDENTIAL AND/OR PROPRIETARY TO THE PHOENIX COMPANY OF CHICAGO INC. AND MAY NOT BE USED FOR MANUFACTURING, REPRODUCED, DISCLOSED TO OTHERS OR FOR ANY OTHER PURPOSE WITHOUT BOTHER 28-0080-2400 VL 9/8/2021 FSCM DWG NO ECN 13793 9/8/2021 ENGINEER REV PLATING OPT. SIZE `BW 5/3/2021 11/26/1997 58167 C 28-0080-2400 OTHER PURPOSE WITHOUT THE EXPRESS WRITTEN CONSENT OF THE PHOENIX COMPANY OF CHICAGO PER ECN 9130 11/6/1907 APPROVED JM 9/8/2021 SHEET 1 DESCRIPTION DATE 1

7