

 $\overline{\downarrow}$

Step 2


B


Insert semi-rigid cable into body until cable bottoms in body. Solder cable jacket into body. Then solder center conductor to center contact of connector.

Step 2

Insert flex cable into body until cable bottoms in body. Solder body to cable braid. Then solder center conductor to center contact of connector.

1






В

Α

Step 3

Clean and inspect the solder joints. Fixture body into a small arbor press. Press cap into body being careful not to damage connector.



WARNING - THIS DOCUMENT CONTAINS TECHNICAL DATA WHOSE EXPORT IS RESTRICTED BY THE ARMS EXPORT CONTROL ACT (TITLE 22, U.S.C., SEC 2751, ET. SEQ.) OR THE EXPORT ADMINISTRATION ACT OF 1979, AS AMENDED, TITLE 50, U.S.C., APP 2401 ET SEQ. VIOLATIONS OF THESE EXPORT LAWS ARE SUBJECT TO SEVERE CRIMINAL PENALTIES. DISSEMINATE IN ACCORDANCE WITH PROVISIONS OF DOD DIRECTIVE 5230.25.

			The
UNLESS OTHERWISE SPECIFIED, PHOENIX WORKMANSHIP STANDARDS APPLY	APPROVALS	DATE	
DIMENSIONS IN INCHES OR (METRIC) DO NOT SCALE PRINTS TOLERANCES ARE:	DRAWN MY	8/17/89	
FRACTIONS: ± 1/64 DECIMALS: XXX±.01 32	CHECKED HN	8/17/89	TITLE
ANGLES: ± 1/2 THE INFORMATION AND DESIGNS	QA		
DISCLOSED IN THIS DOCUMENT ARE CONFIDENTIAL AND/OR PROPRIETARY TO THE PHOENIX COMPANY OF CHICAGO INC. AND	MFG		
MAY NOT BE USED FOR MANUFACTURING, REPRODUCED, DISCLOSED TO OTHERS OR FOR ANY	ENGINEER YT	8/17/89	SIZE A
OTHER PURPOSE WITHOUT THE EXPRESS WRITTEN CONSENT OF THE PHOENIX COMPANY OF CHICAGO	APPROVED HN	8/17/89	SCALE

The **PHOENIX** Company of Chicago, Inc.

22 GREAT HILL RD., NAUGATUCK, CT 06770 WWW.PHOENIXOFCHICAGO.COM

PHONE: (800) 323-9562 FAX:(630) 206-1801

CABLE ASSEMBLY PROCESS FOR:
PkZ® RIGHT ANGLE PLUG, DIRECT
SOLDER TERMINATION

 SIZE
 FSCM
 DWG NO
 REV
 PLATING OPT.

 A
 58167
 26-0520-0860
 K
 K

 SCALE
 F.S.R. #
 SHEET
 2
 OF
 2

2